

SSP.SS.03

Lifting equipment, work equipment and electricity (16 piece puzzle)

Matching statements

Work equipment	PUWER
Lifting equipment	PUWER and LOLER
At least every 6 months	Thorough examination of lifting accessories
At least every 12 months	Thorough examination of lifting equipment (not for lifting persons)
All lifting operations...	Must be properly planned and appropriately supervised
All work and lifting equipment...	Should be subject to pre-use checks
Lifting equipment and accessories must be...	Marked with their rated capacity and configurations of use
Lifting operation categorisation	Basic - Intermediate - Complex
Hired crane	The employing organisation is responsible for the lifting operation
Contract lift	The employing organisation does not plan the lifting operation
High impact eye protection must be worn when using...	Abrasive wheels Cartridge or gas powered fixing tools
Abrasive wheels should only be mounted by...	Trained and authorised personnel
Reduce the severity of electric shock by using...	Battery operated tools
Only use 220-240 volt equipment in conjunction with a...	Residual current device (RCD)
A 'plug-in' RCD should be tested...	Before each use
110-130 volts	Yellow
220-240 volts	Blue
400 volts	Red

Finished puzzle shape:

